

# Bath and shower thermometer JC8740 PIA



## IS THE WATER TOO WARM?

That's what our shower thermometer PIA tells you!

Babies must not catch a cold, but water that is too hot also quickly causes scalding on the sensitive baby skin. To be able to check the water temperature continuously, simply screw our PIA shower thermometer between the shower head and the shower hose. And your baby can really enjoy the fun of bathing: Splash, splash, the granny is suddenly soaking wet!

## Technologies

- Over 41 degrees Celsius, warns against water temperature that is too hot in the shower or bath
- Activated by motion sensor
- Auto off after approx. one hour
- Included in the scope of delivery: 2 x LR44 batteries

## Operation and use

- Checks water temperature in shower and bath
- For the shower hose in the bath and shower

# Bath and shower thermometer JC8740 PIA



Security Tech Germany

Seite 2 von 2

---

## Technical data - Bath and shower thermometer JC8740 PIA

Weight	38 g
colour	white
EAN	4003318731563